



NORTH BALLARAT JUNCTION
SIGNALLING DIAGRAM No: 80/10

(SUPERSEDES 34/10 & 08/09)

Showing Signal and Interlocking Arrangements to come into use on a date to be fixed by circular which will be issued by the Manager Incidents and Safeworking V/Line.

T. BENTLEY
 MANAGER INCIDENTS & SAFEWORKING
 for V/LINE

03/11/2010

