



NOTE:
#1. SSS807U POINTS CLIPPED, LOCKED AND DETECTED NORMAL IN VIADUCT RATIONISATION STAGE 1.
#2. SSS807D, SSS820U AND SSS820D POINTS CLIPPED, LOCKED AND DETECTED NORMAL IN VIADUCT RATIONISATION STAGE 2.

- NOTES:
1. ALL DIMENSIONS IN METRES
2. SIDING DIMENSIONS INDICATE STANDING ROOM
3. THEATRE ROUTE INDICATORS SHOWN THUS:



Bill Lren
MANAGER RAIL STANDARDS
METRO TRAINS MELBOURNE

Rupert Capper
RUPERT CAPPER
MANAGER - SYSTEMS & SAFEWORKING
V/Line



CONTINUED ON FLINDERS ST (WEST) PASSENGER LINES SIGNALLING DIAGRAM (FAS_0009)

CONTINUED ON SOUTHERN CROSS - NORTH MELBOURNE PASSENGER LINES SIGNALLING DIAGRAM (FAB_0002)

CONTINUED ON V/Line PASSENGER LINES SIGNALLING DIAGRAM (FAB 0004)

CONTINUED ON V/Line PASSENGER LINES SIGNALLING DIAGRAM (FAB 0004)